That CAD Girl
jennifer dibona

website: www.thatcadgirl.com
email: thatcadgirl@aol.com
phone: (919) 417-8351
fax: (919) 573-0351

Basic Steps of Parcels Layout, Numbering and Reporting

1. Set the scale and text styles for your drawing in Projects> Drawing Setup.
2. If you are using Parcel Sizing tools to create new lots, first go to Parcels> Parcel Settings and turn OFF the option to "Define Parcels as Sized".

3. Create new lots by either the Parcel Sizing tools or by other methods.
4. Create a new layer named "LOTPOLY" and set the layer current.
5. Use the Autocad BPOLY command to create a new closed polyline inside each lot.
6. Isolate this layer.
7. Go to Parcels> Parcel Settings and set the desired settings

8. Go to Parcels> Define from Polylines and then select each of the lots to be defined. Select them in the order that you want the lots numbered.
9. Export to LandXML format: Projects> Export LandXML
10. Select some or all of the parcel definitions to be exported and hit OK. Select the location and provide a file name.
11. Go to the Desktop and launch LandXML Reporting.
12. Go to File> Open Data File
13. Navigate through the tabs. First select the "Forms" tab to specify the type of form to be output.
14. Next, go to the "Settings" tab to specify your company, client and project data.
15. Next, go to the "Output" tab to see the results.